Scope of	Work for Property Loc	ated at	:	4333 North 37th Street					
	Property is: Single Fan	nily 🗵	Duplex	□ Other □					
Date:	3/7/2016								
take no respo		after the in	spection dat	e, or for omissions throu	e, the Redevelopment Authority, and their re Igh error or oversight. The list does not ned IE programs.				
Exterior	Condition Report								
Location Site	Required Work Landscaping	n/a ☑	Yes □	Note/Comments Self Help	\$	Cost			
	Steps/Handrails	n/a ☑	Yes □		\$	_			
	Service walks	n/a ☑	Yes □		\$	_			
	Fencing	n/a ☑	Yes □		\$	_			
	Parking	n/a ☑	Yes □		\$	_			
	Retaining walls	n/a ☑	Yes □		\$				
	Other	n/a □	Yes □		\$				
_	Other	n/a □	Yes □		\$	_			
Garage	Singles: repair	n/a ☑	Yes □		\$				
	Shingles: Roof over existing	n/a ☑	Yes □		\$				
	Shingles:Tear off & re-roof	n/a □	Yes ☑		\$	1,650.00			
	Gutters/downspouts	n/a ☑	Yes □		\$				
	Flashing	n/a ☑	Yes □		\$				
	Eaves	n/a ☑	Yes □		\$				
	Siding	n/a ☑	Yes □		\$				
	Doors	n/a □	Yes ☑		\$	1,200.00			
	Windows	n/a ☑	Yes □		\$				
	Slab	n/a ☑	Yes □		\$				
	Paint	n/a ☑	Yes □		\$				
	Electrical	n/a ☑	Yes □		\$				
	Other	n/a □	Yes □		\$				
Porches	Roof	n/a ☑	Yes 🗆		\$				
	Deck-upper	n/a ☑	Yes 🗆		\$				
	Decklower	n/a □	Yes 🗹		\$	1,800.00			
	Steps/handrails	n/a □	Yes 🗹		\$	650.00			
	Ceiling	n/a ☑	Yes 🗆		\$				
	Guardrails	n/a □	Yes ☑		\$	250.00			
	Structural	n/a ☑	Yes 🗆		\$				
	Paint	n/a □	Vec 🖂		Φ.	350.00			

n/a □ Yes ☑ repair column

\$

800.00

Other

House

Chimney	n/a ☑	Yes □	\$	
Shingles: repair	n/a ☑	Yes □	\$	
Shingles: Roof over existing	n/a ☑	Yes □	\$	
Shingles:Tear off & re-roof	n/a □	Yes 🗸	\$	7,800.00
Gutters/downspouts	n/a □	Yes 🗹	\$	850.00
Flashing	n/a □	Yes 🗹	\$	200.00
Eaves	n/a ☑	Yes □	\$	
Siding	n/a _☑	Yes □		
Storm Doors	n/a ☑	Yes □	\$	
Prime ("main") Doors	n/a ☑	Yes □	\$	
Storm Windows	n/a □	Yes ☑	\$	400.00
Prime ("main") Windows	n/a □	Yes ☑	\$	800.00
Paint	n/a □	Yes ☑	\$	350.00
Foundation	n/a _□	Yes ☑		250.00
Electrical	n/a ☑	Yes □	\$	
Other	n/a □	Yes □	\$	
Other	n/a □	Yes □	\$	
Other	n/a □	Yes 🗆	\$	
Other	n/a □	Yes □	<u> </u>	

Exterior: Estimated Cost:* \$ 17,350.00
*average contracted cost. Actual costs may vary. Self help will reduce the amount.

	Unit: Entire unit (single family) Upper unit of duplex Required Work	✓□				Lower unit of duplex Other			
Heating	•								
	Repair/replace boiler	n/a	7	Yes					\$
	Repair radiation	n/a	1	Yes [\$
	Repair/replace furnace	n/a		Yes [V	_			\$ 3,000.00
	Repair ductwork	n/a	1	Yes [_			\$
	Replace thermostat	n/a		Yes [V	_			\$ 100.00
	Repair/replace grilles	n/a	7	Yes [\$
Electrical	Tune boiler/furn. insp ht exchang	en/a	7	Yes [_			\$
Liectrical	Repair/replace receptacles	n/a	7	Yes [_			\$
	Repair/replace switches	n/a	7	Yes [_			\$
	Repair/replace fixtures	n/a	4	Yes [_			\$
	Install outlets and circuits	n/a	7	Yes [=			\$
	Install outlets and circuits	n/a	1	Yes [_			\$
	Install outlets and circuits	n/a	7	Yes [_			\$
	Install outlets and circuits	n/a	7	Yes [\$
	Upgrade service	n/a _	7	Yes [_			\$
	Other	n/a _		Yes [_			\$
Dhambian	Other	n/a		Yes [_			\$
Plumbing	Repair/replace kitchen sink	n/a		Yes [7				\$ 1,500.00
	Repair/replace kitchen sink fauce	n/a _		Yes [7	_			\$ 450.00
	Repair/replace tub	n/a	7	Yes [=			\$
	Repair/replace tub faucet	n/a		Yes [7	_			\$ 450.00
	Repair/replace toilet	n/a	7	Yes [\$
	Repair/replace lavatory	n/a		Yes [4	_			\$ 350.00
	Repair/replace lavatory faucet	n/a _		Yes	7				\$ 300.00
	Repair/replace wash tub	n/a		Yes [7				\$ 750.00
	Repair/replace wash tub faucet	n/a		Yes [7				\$ 350.00
	Unclog piping:	n/a	7	Yes [\$
	Repair drain/waste/vent piping	n/a	7	Yes [_		_	\$
	Repair water piping	n/a		Yes [7				\$ 1,100.00
	Repair/replace water heater	n/a		Yes [7				\$ 850.00
	Other	n/a		Yes [\$
	Other	n/a		Yes [\$

Windows								
	Replace broken glass	n/a	1	Yes		_	\$	
_	Repair or replace sash	n/a	4	Yes		~	\$	
Doors	Repair or replace doors	n/a		Yes	7	-	\$	800.00
	Repair or repl. locks/latches	n/a	7	Yes		Self Help	\$	
Walls/Ceiling	Repair or repl. @ defective	n/a		Yes	7		\$	2,800.00
Paint								
	Repair or repl. @ defective	n/a		Yes	✓		\$	1,200.00
Fire Safety	Install smoke/CO alarm:bsmt.	n/a		Yes	7	Self Help	\$	40.00
	Install smoke/CO alarm: 1st flr.	n/a		Yes	7	Self Help	\$	40.00
	Install smoke/CO alarm: 2nd flr.			Yes		Self Help	\$	
Handrails	Repair/replace defective	n/a		Yes	<u> </u>	Self Help	\$	125.00
Stairs	Repair defective	n/a	П	Yes	7	•	\$	250.00
Floors	Repair defective	n/a		Yes	<u>v</u>		\$	2,200.00
Other	Tiepaii derective						·	2,200.00
		n/a		Yes			\$	
		n/a		Yes		_	\$	
		n/a		Yes			\$	
		n/a		Yes		-	\$	
						Interior: Estimated Cost:	\$	16,655.00
						Total Exterior and Interior Cost:*	\$	34,005.00
						*average contracted cost. Actual costs may vary. Self help will reduce ti	he amount.	

Inspected by: Mark Pelzek Date: 3/7/16

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.